



Dear Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Dorman Products has decided that a defect which relates to motor vehicle safety exists in certain aftermarket replacement control arms. As a result of this determination, Dorman Products is recalling part #'s 520-121, 520-122, 2410121 and 2410122 which **were sold for replacement use** on the following makes and models:

MAKE	MODEL	YEAR	MAKE	MODEL	YEAR
CHEVROLET TRUCK	BLAZER	1994-92	GMC TRUCK	C2500 PICKUP: SIERRA	1998-89
CHEVROLET TRUCK	C1500 PICKUP	1999-88	GMC TRUCK	C2500 PICKUP: SIERRA XC	1998-89
CHEVROLET TRUCK	C1500 SUBURBAN	1999-92	GMC TRUCK	C2500 SUBURBAN	1999-92
CHEVROLET TRUCK	C2500 PICKUP	2000-88	GMC TRUCK	C3500 PICKUP	2000-88
CHEVROLET TRUCK	C2500 SUBURBAN	1999-92	GMC TRUCK	C3500 PICKUP: SIERRA	1997-89
CHEVROLET TRUCK	C3500 PICKUP	2000-88	GMC TRUCK	C3500 PICKUP: SIERRA XC	1997-89
CHEVROLET TRUCK	EXPRESS 1500	2002-96	GMC TRUCK	SAVANA 1500	2002-96
CHEVROLET TRUCK	EXPRESS 2500	2002-96	GMC TRUCK	SAVANA 2500	2002-96
CHEVROLET TRUCK	EXPRESS 3500	2002-96	GMC TRUCK	SAVANA 3500	2002-96
CHEVROLET TRUCK	TAHOE	2000-95	GMC TRUCK	YUKON	1999-92
GMC TRUCK	C1500 PICKUP	1999-88	GMC TRUCK	YUKON XL 1500	2000
GMC TRUCK	C1500 PICKUP: SIERRA	1997-89	GMC TRUCK	YUKON XL 2500	2000
GMC TRUCK	C1500 PICKUP: SIERRA XC	1997-89	GMC TRUCK	YUKON: DENALI	2000-99
GMC TRUCK	C1500 SUBURBAN	1999-92	GMC TRUCK	YUKON: SLE	2000
GMC TRUCK	C2500 PICKUP	2000-88	GMC TRUCK	YUKON: SLT	2000

Only control arms with the part numbers stated above, purchased after November 1, 2010, are included in this recall.

Defect: A potential manufacturing process defect could result in the control arm stud fracturing prematurely without warning, thus impairing steering and handling of the vehicle.

Remedy: Dorman Products wishes to recover as many of these parts as possible. Dorman believes that you currently have or have previously owned a motor vehicle in which one of these parts was installed. For this reason we ask that you arrange for your dealer or independent automotive repair facility to replace this part without delay. Dorman will provide replacement parts and will reimburse you or the repair facility for labor. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. In order to qualify for this reimbursement, you must send original invoices and receipts to **Dorman Products, Inc., 3400 East Walnut Street, Colmar, PA 18915, Attn: Control Arm Recall.** For more information please call our toll free hotline at **1-800-523-2492.** Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer or independent automotive repair facility is unwilling or is unable to remedy this defect within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>. Thank you for your patience and support in helping us to keep you safe.

Sincerely,

Kevin Gallagher,
VP Engineering & Quality

NEW PRODUCTS. NEW SOLUTIONS. NEW OPPORTUNITIES.