

A I R T E X P R O D U C T S , L P

AIRTEX AUTOMOTIVE DIVISION

To: Airtex Fuel Pump Customers

Subject: E3592M / E8489M Fuel Pump Module Safety Recall FP030911-1

Vehicle Application: E3592M 06-04 Chevrolet Malibu V6-3.5L
 06-04 Chevrolet Malibu L4-2.2L
 2006 Chevrolet Malibu V6-3.9L
 E8489M 09-03 SAAB 9-3 L4-2.0L

Reference: NHTSA Campaign ID Number 11E009000


Airtex has determined a potential product safety issue involving E3592M and E8489M fuel pump modular assemblies. While no safety-related occurrences have been reported in the field, Airtex is taking steps to avoid any potential issues.

These part numbers are purchased from the OE supplier. Airtex was notified by the OE supplier that an out-of-tolerance component could potentially cause an issue with the operation of the pump. This recall not only affects Airtex, but many other aftermarket and original equipment suppliers.

To avoid any potential issues, it is necessary that you and your customers contain and return all E3592M and E8489M fuel pump modules marked with manufacturing date codes 200 through 081.

Affected Date Codes

200	210	220	230
240	250	260	270
280	290	300	310
320	330	340	350
360	370	380	390
400	410	420	430
440	450	460	470
480	490	500	510
520	011	021	031
040	051	061	071
081			



Date Code Location

Fuel pumps must be returned freight collect to the address listed below within 30 days. To ensure proper shipment tracking of the affected product, **please call 800-880-3056 to obtain an RGA number.** Make reference to Fuel Pump Safety Recall FP030911-1 in correspondence, packing and shipping documents.



407 West Main Street
 Fairfield, IL 62837
 800.880.3056
 www.airtexproducts.com

A I R T E X P R O D U C T S , L P

AIRTEX AUTOMOTIVE DIVISION

Fuel pump modules sold and installed during the time period from May 17, 2010 to February 14, 2011 may be affected and must be returned. In order to facilitate this, **please provide Airtex with names and addresses of all customers who may have purchased and installed the affected fuel pump modules during the specified time period.** You may respond to Airtex via mail, email, or fax.

Airtex Products
407 West Main Street
Fairfield, IL 62837
Fax: 618-842-4069
customerservice@airtexproducts.com

Vehicle owners and installers with questions should be instructed to call **888-867-3759**.

Airtex will provide full merchandise credit for the affected units.

Thank you in advance for your assistance in ensuring that all affected products are returned to Airtex.

Sincerely,

AIRTEX PRODUCTS, LP



Pam Schell
Customer Service Manager



407 West Main Street
Fairfield, IL 62837
800.880.3056
www.airtexproducts.com