



Campaign # 10E-059
February 2, 2011

Dear Valued Customer:

This notice is sent to you on behalf of Advance Auto Parts and in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Federal-Mogul Corporation has decided that a defect which relates to motor vehicle safety exists in certain Federal-Mogul aftermarket control arm assemblies, to include part numbers K7425, K7427, 10945 and 10946, manufactured for: Chrysler Cirrus 1995-2000; Sebring Convertible and Sedan only 1996-2006; Dodge Stratus Sedan 2001-2006; Stratus all 1995-2000; and Plymouth Breeze 1996-2000 vehicles. Therefore, Federal-Mogul is recalling these specific control arm assemblies. Federal-Mogul will replace these parts without charge.

Advance Auto Parts records indicate that you have purchased one or more of these part numbers during the identified time period.

1. Identification of equipment affected:

Federal-Mogul packaged and sold the recalled aftermarket control arm assemblies between February 15, 2010 and December 20, 2010 under the brand names MOOG® and TRW®. The specific part numbers being recalled, affected date codes, and vehicle application information which may relate to parts Advance Auto Parts records indicate were sold to you are listed in the enclosed Technician Service Instructions...

2. Description of possible malfunction and safety evaluation:

The ball joint on the control arm assembly can fail causing the ball stud to wear through the control arm housing resulting in noise and/or separation of the ball stud from the housing. If there is a separation of the ball stud from the housing, a vehicle crash may occur.

3. Vehicle owner precautions:

The subject control arm assemblies were manufactured for aftermarket use. Owners of these parts should have them removed and replaced as soon as possible.

4. Owner remedy measures:

Federal-Mogul wishes to recover as many of these parts as possible. Therefore, we respectfully request that you return the subject part numbers to your local Advance Auto Parts store. Recalled control arm assemblies from your customers also should be returned to Advance Auto Parts.

For return of unused recalled control arm assemblies, please return the product to your local Advance Auto Parts store. The return package should be clearly marked with "**reference control arm assembly recall**".

The return of the part(s) will be at no cost to you. Upon return of the part(s), your account will be credited for the part(s). For replacement of recalled product, you will need to order the appropriate stock number from your local Advance Auto Parts store.

If the part is suspected to have been installed on a vehicle, Federal-Mogul will pay for inspection and, if the part is covered by the recall, replacement of the defective part(s), as well as shipping charges. In order to qualify for inspection reimbursement, the enclosed inspection reimbursement form must be written-up and submitted to Federal-Mogul, along with documentation. If you, during your inspection, find a recalled control arm assembly, please remove and return the part, along with your invoice and proof of purchase to your local Advance Auto Parts store. The return package should be clearly marked “**reference control arm assembly recall**”. If you are unable or unwilling to inspect or remove the part(s), please call the Federal-Mogul hotline at 1-877-489-6659.

Federal-Mogul will reimburse a maximum of \$20 for the labor cost of inspection of the suspect part(s). Labor reimbursement of up to \$100 for one control arm assembly and up to \$152 for both control arm assemblies will be reimbursed for inspection and replacement of the applicable recalled part(s). Reimbursement will be paid for inspection only or for product replacement with associated labor costs (see above) – not both. For assistance on inspection or replacement reimbursement, contact your local Federal-Mogul Sales Representative.

5. Violation of federal law to sell equipment covered by this recall:

No recalled control arm assemblies currently in your inventory may be sold as it is a violation of federal law for a dealer to sell a recalled item of motor vehicle equipment.

6. Owner complaint process:

The owner of a vehicle with a recalled control arm assembly may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>, if the owner believes that Federal-Mogul has failed or is unable to remedy without charge the condition outlined above within a reasonable time.

Please review the above information and contact your local Advance Auto Parts store or call the Federal-Mogul hotline at 1-877-489-6659 with any questions. Our commitment to product quality is at the forefront of all we do at Federal-Mogul. Our dedication to manufacturing mastery is supported by all within the organization.

Federal-Mogul apologizes for any inconvenience. We know, however, that you share our concern for vehicle safety. We appreciate your immediate response to this matter.

Sincerely,

Mark Boyle
Director, Steering Products
Federal-Mogul Corporation